The Pennsylvania Ignition Interlock Program

A presentation by the Pennsylvania Department of Transportation and the Pennsylvania DUI Association





PA DUI Association Headquarters



2413 North Front Street Harrisburg, PA 17110

Phone: 717-238-4354

Ignition Interlock & the PA DUI Association

- In January of 2002, Penn DOT awarded a contract to the Pennsylvania DUI Association for the Pennsylvania Ignition Interlock Quality Assurance Program.
- The program oversees the quality assurance aspect of the ignition interlock devices approved and used in Pennsylvania, provide technical assistance to manufacturers, service providers and ignition interlock users; and ensures that ignition interlock manufacturers and service providers adhere to the Penn DOT specifications.

Ignition Interlock Quality Assurance Program

- Compiles a directory of service providers
- Compiles statistics
- Monitors manufactures/service providers for compliance
- Provide technical assistance to Ignition Interlock clients and service providers
- Conducts quality assurance inspections of service providers/center, including the review of interlock data
- Survey participating clients

§3805: Ignition Interlock

- Each motor vehicle owned must be equipped with an ignition interlock system
- If there are no motor vehicles owned or registered individuals must so certify to the Department
- Offenders may no longer opt out of ignition interlock

Applying for an Ignition Interlock System/License

- Restoration Requirement letter will be sent thirty (30) days prior to their eligibility date
- An Ignition Interlock Application (DL3731) form will be included
- The customer will be directed to PADUI web-site, or will contact PADUI for a list of vendors in their area

Ignition Interlock Process

- Offender makes appointment with Service Provider
- Completes Self Certification Form DL-21SC
- If applicable, checks for Hardship Exemption
- If applicable, completes Employment Exemption Affidavit
- Ignition Interlock Device installed on all owned/registered vehicles
- > Offender receives Restricted License

Exceptions to the Rule

If no vehicle is owned, a DL21-SC form must be completed by the vendor and submitted to the Department of Transportation. Pennsylvania Drivers Licenses : Unrestricted VS Restricted License Notice Any Differences?





What is Ignition Interlock?

 An Ignition interlock is a device that is installed into a motor vehicle to prohibit individuals under the influence of alcohol from starting the vehicle.



What types of vehicles can utilize this lifesaving technology?

ANY vehicle owned by an individual with multiple offenses in the Commonwealth

> Motorcycles, RV's



PA Ignition Interlock Providers

- > Alcolock of PA
- > Alcohol Detection Systems, Inc.
- Blow and Drive (BDI) Interlock Services
- > Draeger Interlock
- Guardian Interlock
- Interlock of Pennsylvania
- Intoxalock (CST)
- Low Cost Interlock Services (LCI)
- Smart Start
- *Allegheny County Ignition Interlock Services
- *Dauphin County Ignition Interlock Services

What Does an Ignition Interlock Device Look Like?




Intoxalock (Blow Inhale Blow)




Smart Start & Allegheny County (Blow and Hum)



Alcolock GR Wireless (Blow then Hum)





Alcohol Detection Systems (Blow-Suck-Hum)





Interlock of PA (Short blow, Suck, Long blow)



Low Cost Interlock (Straight Blow)



Dauphin County ("Dooooooo")



Blow and Drive (Straight Blow)

> How the device works: Based on NHTSA guidelines The device indicates the results of the breath test thru pass/fail signals (No BAC Display)

If pass, allows 3 minutes to start car and allows a 3 minute sample free restart period in case of a stall

How the device works:

- > A driver must blow a breath sample (≈1.5L) into the mouthpiece to start the vehicle
- The device analyzes and measures the breath sample for alcohol concentration
- If alcohol is detected and exceeds 0.025mg, the device will not allow the vehicle's engine to start

How the device works:

 The device is capable of random retesting during the operation of the vehicle (intervals of 5-15-45 minutes)

 The device is capable of detecting circumvention attempts (shorting of device) and preventing bogus or filtered air sample (air compressors or balloons)

How the device works

Device enters into early recall requiring service when:

1 running retest violation

➤ 1 event of tampering

➤ 1 illegal start violation

► 3 High BACs


➢ 90% full data logger memory

How the device works:

Ignition Lockouts

 \succ

- Initial lockout due to breath alcohol of .025 or more = 5 minutes
- Subsequent lockouts = 30 minutes
- > 3 consecutive lockouts = Permanent Lockout and must be reset by service provider



Sample Data Logger

02-10-2010

9:39:05 PM Car Restart 9:40:33 PM Car Stop 9:46:05 PM PASSED: BAC=.000 PK=-15 BL=-18 AT=28.8C BT=33. 1C RV=50 T=1.85s 9:46:10 PM Car Start 9:50:54 PM Car Stop

02-11-2010 3:32:24 PM FAILED: BAC=.038 PK=172 BL=-12 AT=14.6C BT=29.0C RV=51 T=10.57s 7:52:05 PM Invalid sample – pressure 7:52:45 PM FAILED: BAC=.031 PK=149 BL=-1 AT=10.7C BT=29.9C RV=50 T=9.93s

Sample Data Logger

02-13-2010

2:09:12 AM PASSED: BAC=.000 PK=-1 BL=-6 AT=3.2C BT=26.6C RV=51 T=2.01s 2:09:20 AM Car Start 2:12:49 AM Car Stop 2:15:03 AM Car Restart 2:15:16 AM REJECTED: Too Soft (MN=42 AN=0 Q1=11 HC=0 SC=0 Q2=0)

02-17-2010 1:15:11 AM Car Stop On Retest 1:21:22 AM PASSED: BAC=.000 PK=33 BL=-11 AT=11.6C BT=30.0C RV=5- T=10.81s 1:21:27 AM Car Start 1:26:59 AM RETEST-PASSED: BAC=.000 PK=31 BL=-6 AT=13.4C BT=31.5C RV=50 T=7.77s 1:37:21 AM Car Stop 4:22:36 AM FAILED: BAC=.173 PK=833 BL=-9 AT=7.1C BT=27.6C RV=50 T=11.13s

§3808 (a)(1)

- > Illegally operating a motor vehicle not equipped with an ignition interlock device
- > Misdemeanor Offense
- > Fine \$300 to \$1000
- > Up to 90 days incarceration

§3808 (a)(2)

- > Illegally operating without an interlock system .025% BAC and or controlled substance:
- > 3rd Degree Misdemeanor
- > \$1000 fine
- > Minimum 90 days incarceration

§3808 (b)

- > Tampering with an ignition interlock system:
- > Misdemeanor
- > Fine of \$300 to \$1,000
- > Up to 90 days incarceration

Tampering continued:

Defined:

- Physical act intended to alter or interfere with the device function.
- Means of using another individual to provide a breath sample.
- Providing a breath sample for the purpose of bypassing a device.

§3808: Penalties cont'd

- License Consequences for Non-compliance of §3805:
- Ist conviction results in one year extension of the ignition interlock program from the date of conviction
- 2nd conviction during the same interlock period results in a one year license suspension and a year of ignition interlock

Circumvention Examples

- Having a sober passenger blow into device.
- Family, friend or another passenger
- > Using some form of supplemental air.
 - » Blowing into balloon before drinking
 - > Air compressor
 - Compressed air cans

Circumvention Examples


- Removal of device by client.
- Insertion of toggle/relay switches.
- Compression Starting a vehicle.
- ("Bump Starting" "Popping the clutch")

Example of Circumvention (Client Removal)



Examples of clients bypassing the device (Inserting a Toggle Switch)







Tamper Notification

- Service Provider discovers attempt to tamper or circumvent device. Sends Information to PA DUI Assoc.
- PA DUI Association will forward the tamper and all documentation to the District Attorney in the County where the individual was convicted.

BUREAU OF DRIVER LICENSING

Ignition Interlock (II) Device & License

Required Maintenance

- Must keep appointments with II Vendor to download data from II device. Every 60 days (first monitoring appointment <u>must be</u> within 30 days after the installation of the device).
- If an individual fails to keep appointment, tampers with or removes II device prior to the 1 year requirement, II license will be cancelled.
- To have the cancel removed, must comply with II Vendor's request for service or re-install II device.

BUREAU OF DRIVER LICENSING


Ignition Interlock (II) License (continued)

> Extending II Period

Failure to keep appointment with II Vendor
Removal of II device prior to 1 year term
Conviction for driving a vehicle without a II device
New suspension during II period

Non-Compliance

Service Provider notifies BDL when:



Driver has purchased a vehicle and did not get device installed

Driver requested an unauthorized removal of device

Non Compliance Report

Form DL – 373

- Sent by Service Provider to BDL
- Violation Information
 - Driver has failed to make vehicle(s) available for maintenance
 - Driver has purchased a vehicle and did not get device installed
 - Driver requested an unauthorized removal of device

ACT 33 of 2016 effective 8/25/2017

75 Pa.C.S.§ 3805 Ignition Interlock

Amends the existing ignition interlock statute (which previously applied only to second-time offenders) to require individuals who have violated §3802,1547,or 3808(C) to comply with the following:

ACT 33 of 2016

- Any motor vehicle operated by the individual must have ignition interlock.
- If no vehicles are owned or operated they must certify this to PennDOT
- This does not include persons who are subject to penalties under §3804(a)(1) and does not have a prior offense as defined in §3806.

Ignition Interlock Limited License ACT 33

75 Pa.C.S.§1556

This newly created section applies to individuals who have been suspended for DUI under the following sections:

- a. 75 Pa.C.S.§3802 (DUI)
- b. 75 Pa.C.S. §1547 (Refusal)

does not apply to first offense general impairment or those entering into ARD

Suspension Eligibility (ACT33)

For violation of §1547(b); Refusal

- serve <u>six months</u> of the suspension imposed or <u>twelve months</u> maximum suspension. (interlock still required for 12 months).
- §1547(b)(1)(ii) serve <u>nine months</u> suspension or <u>eighteen months</u> maximum suspension. (II still required)

Suspension Eligibility (ACT 33)

- For a suspension under §3804(e) (first offense) relating to DUI penalties, the individual is eligible for early interlock
- immediately, and must have the interlock on the vehicle for one year, or serve the twelve month hard suspension and will still be required to install an interlock device for twelve months.

Act 33 of 2016

		DUI C	DFFENSES		
OFFENSE	NUMBER	Suspension Length	Eligible for Early Interlock	When Eligible	INTERLOCK PERIOD
	First	NONE	N/A	N/A	N/A
Gen Imp	Second	12 Months	Yes	After 6 Months	1 Year
	Third or Subsequent	12 Months	Yes	After 6 Months	
High Rate Minor School/CDL Vehicles	First	12 Months	Yes	Immediately	1 Year
	Second	12 Months	Yes	After 6 Months	1 Year
	Third	18 Months	Yes	After 9 Months	1 Year
	Fourth or Subsequent	18 Months	Yes	After 9 Months	1 Year
Highest Rate Gen Imp -Refusal Controlled Substances	First	12 Months	Yes	Immediately	1 Year
	Second	18 Months	Yes	After 9 Months	1 Year
	Third or Subsequent	18 Months	Yes	After 9 Months	1 Year
ARD Offenses	N/A	N/A	NO	N/A	N/A
OFFENSE	NUMBER		NSION OFFENSES ELIGIBLE FOR Early INTERLOCK	WHEN ELIGIBLE	INTERLOCK PERIOD
Refusal to Submit to Chemical Testing for Violation of 3802	First	12 Months	Yes	After 6 months	1 Year
	Second (or prior conviction for DUI)	18 Months	Yes	After 9 Months	1 Year
Ignition Interlock Violations under 3808	First	N/A	N/A	N/A	1 Year (from conviction
	Second or Subsequent	1 Year	No	N/A	1 Year
Refusal to Submit to Chemical Testing for Violation of 1543(b)(1.1) or Igntion Interlock Violation of 3808(a)(2)	First	6 Months (If no suspension for 3802 imposed)	No	6 Months	1 Year
	Second or Subsequent	6 Months (If no suspension for 3802 imposed) IILL Recalled	No	6 Months	1 Year

Requirements for De-Installs under ACT 33

Ignition Interlocks are still required for oneyear in order for the individual to be eligible for an unrestricted license.

In order to apply for and receive an unrestricted license the individual must do the following:

Provide proof that the program has been completed

Deinstalls under ACT 33

- > Vendor provides certificate that during the last two months of the program there were no:
- > attempts to start the vehicle with BrAC at or above .08%
- Failures to take or pass a re-test
- Failure to report for calibration, repair, monitoring, or inspection.

2017- Total Number of Installs by County

Adams 76 Allegheny 581 Armstrong 40 Beaver 74 Bedford 33 Berks 171 Blair 83 Bradford 39 Bucks 349 Butler 107 Cambria 63 Carbon 33 Centre 78 Chester 229 Clarion 21 Clearfield 31 Clinton 25 Columbia 24 Crawford 51 Cumberland 183 Dauphin 153 Delaware 182 Elk 13 Erie 54 Forest 6 Franklin 1001 Fulton 7 Greene 14 Huntington 31 Indiana 44 Jefferson 20 Juniata 12		
Armstrong 40 Beaver 74 Bedford 33 Berks 171 Blair 83 Bradford 39 Bucks 349 Butler 107 Cambria 63 Cameron 2 Carbon 33 Centre 78 Chester 229 Clarion 21 Clearfield 31 Clinton 25 Columbia 24 Crawford 51 Cumberland 183 Dauphin 153 Delaware 182 Eik 13 Erie 1002 Fayette 54 Forest 6 Franklin 101 Fulton 7 Greene 14 Huntington 31 Indiana 44	Adams	76
Antibuling 74 Beaver 74 Bedford 33 Berks 171 Blair 83 Brafford 39 Bucks 349 Butler 107 Cambria 63 Cameron 2 Carbon 33 Centre 78 Chester 229 Clarion 21 Clearfield 31 Clinton 25 Columbia 24 Crawford 51 Cumberland 183 Dalphin 153 Delaware 182 Elk 13 Erie 1002 Fayette 54 Forest 6 Franklin 101 Fulton 7 Greene 14 Huntington 31 Indiana 44	Allegheny	581
Bedford 33 Bedford 33 Berks 171 Blair 83 Bradford 39 Bucks 349 Butler 107 Cambria 63 Cameron 2 Carbon 33 Centre 78 Chester 229 Clarion 21 Clearfield 31 Clinton 25 Columbia 24 Crawford 51 Cumberland 183 Dalphin 153 Delaware 182 Elk 13 Erie 1002 Fayette 54 Forest 6 Franklin 101 Fulton 7 Greene 14 Huntington 31 Indiana 44	Armstrong	40
Berks 171 Blair 83 Bradford 39 Bucks 349 Butler 107 Cambria 63 Cambria 63 Cambron 2 Carbon 33 Centre 78 Chester 229 Clarion 21 Clearfield 31 Clinton 25 Columbia 24 Crawford 51 Cumberland 183 Dalaware 182 Elk 13 Erie 1002 Fayette 54 Forest 6 Franklin 101 Fulton 7 Greene 14 Huntington 31 Indiana 44	Beaver	74
Blair 83 Bradford 39 Bucks 349 Butler 107 Cambria 63 Carbon 33 Centre 78 Chester 229 Clarion 21 Clearfield 31 Clinton 25 Columbia 24 Crawford 51 Cumberland 183 Dauphin 153 Delaware 182 Elk 13 Erie 1002 Fayette 54 Forest 6 Franklin 101 Fulton 7 Greene 14 Huntington 31 Indiana 44	Bedford	33
Bradford 39 Bradford 39 Bucks 349 Butler 107 Cambria 63 Carbon 33 Centre 78 Chester 229 Clarion 21 Clearfield 31 Clinton 25 Columbia 24 Crawford 51 Cumberland 183 Dauphin 153 Delaware 182 Elk 13 Erie 1002 Fayette 54 Forest 6 Franklin 101 Fulton 7 Greene 14 Huntington 31 Indiana 44	Berks	171
Bucks 349 Butler 107 Cambria 63 Cameron 2 Carbon 33 Centre 78 Chester 229 Clarion 21 Clearfield 31 Clinton 25 Columbia 24 Crawford 51 Cumberland 183 Dauphin 153 Delaware 182 Elk 13 Erie 102 Fayette 54 Forest 6 Franklin 101 Fulton 7 Greene 14 Huntington 31 Indiana 44	Blair	83
Butler 107 Cambria 63 Cameron 2 Carbon 33 Centre 78 Chester 229 Clarion 21 Clearfield 31 Clinton 25 Columbia 24 Crawford 51 Cumberland 183 Dauphin 153 Delaware 182 Eik 13 Erie 1002 Fayette 54 Forest 6 Franklin 101 Fulton 7 Greene 14 Huntington 31 Indiana 44	Bradford	39
Cambria 63 Cameron 2 Carbon 33 Centre 78 Chester 229 Clarion 21 Clearfield 31 Clinton 25 Columbia 24 Crawford 51 Cumberland 183 Dalaware 182 Elk 13 Erie 102 Fayette 54 Forest 6 Franklin 101 Fulton 7 Greene 14 Huntington 31 Indiana 44	Bucks	349
Cameron 2 Carbon 33 Carbon 33 Centre 78 Chester 229 Clarion 21 Clearfield 31 Clinton 25 Columbia 24 Crawford 51 Cumberland 183 Dauphin 153 Delaware 182 Elk 13 Erie 1002 Fayette 54 Forest 6 Franklin 101 Fulton 7 Greene 14 Huntington 31 Indiana 44	Butler	107
Carbon 33 Centre 78 Chester 229 Clarion 21 Clearfield 31 Clinton 25 Columbia 24 Crawford 51 Cumberland 183 Dauphin 153 Delaware 182 Elk 13 Erie 102 Fayette 54 Forest 6 Franklin 101 Fulton 7 Greene 14 Huntington 31 Indiana 44	Cambria	63
Centre 78 Chester 229 Clarion 21 Clearfield 31 Clinton 25 Coumbia 24 Crawford 51 Cumberland 183 Dauphin 153 Delaware 182 Elk 13 Erie 102 Fayette 54 Forest 6 Franklin 101 Fulton 7 Greene 14 Huntington 31 Indiana 44	Cameron	2
Chester 229 Clarion 21 Clearfield 31 Clinton 25 Columbia 24 Crawford 51 Cumberland 183 Dauphin 153 Delaware 182 Elk 13 Erie 102 Fayette 54 Forest 6 Franklin 101 Fulton 7 Greene 14 Huntington 31 Indiana 44	Carbon	33
Clarion 21 Clearfield 31 Clinton 25 Columbia 24 Crawford 51 Cumberland 183 Dauphin 153 Delaware 182 Elk 13 Errie 102 Fayette 54 Forest 6 Franklin 101 Fulton 7 Greene 14 Huntington 31 Indiana 44	Centre	78
Clearfield 31 Clinton 25 Columbia 24 Crawford 51 Cumberland 183 Dauphin 153 Delaware 182 Elk 13 Errie 102 Fayette 54 Forest 6 Franklin 101 Fulton 7 Greene 14 Huntington 31 Indiana 44	Chester	229
Cliniton 25 Columbia 24 Crawford 51 Cumberland 183 Dauphin 153 Delaware 182 Elik 13 Erie 102 Fayette 54 Forest 6 Franklin 101 Fulton 7 Greene 14 Huntington 31 Indiana 44	Clarion	21
Columbia 24 Crawford 51 Cumberland 183 Dauphin 153 Delaware 182 Elk 13 Erie 102 Fayette 54 Forest 6 Franklin 101 Franklin 101 Franklin 7 Greene 14 Huntington 31 Indiana 44 Jefferson 20	Clearfield	31
Crawford 51 Cumberland 183 Dauphin 153 Delaware 182 Elk 13 Erie 102 Fayette 54 Forest 6 Franklin 101 Fulton 7 Greene 14 Huntington 31 Indiana 44 Jefferson 20	Clinton	25
Cumberland 183 Dauphin 153 Delaware 182 Elk 13 Erie 102 Fayette 54 Forest 6 Franklin 101 Fulton 7 Greene 14 Huntington 31 Indiana 44	Columbia	24
Dauphin 153 Delaware 182 Elk 13 Erie 102 Fayette 54 Forest 6 Franklin 101 Fulton 7 Greene 14 Huntington 31 Indiana 44 Jefferson 20	Crawford	51
Delaware 182 Elk 13 Erie 102 Fayette 54 Forest 6 Franklin 101 Fulton 7 Greene 14 Huntington 31 Indiana 44 Jefferson 20	Cumberland	183
Image: Second	Dauphin	153
Erie 102 Fayette 54 Forest 6 Franklin 101 Fulton 7 Greene 14 Huntington 31 Indiana 44 Jefferson 20	Delaware	182
Fayette 54 Forest 6 Franklin 101 Fulton 7 Greene 14 Huntington 31 Indiana 44 Jefferson 20	Elk	13
Forest 6 Franklin 101 Fulton 7 Greene 14 Huntington 31 Indiana 44 Jefferson 20	Erie	102
Franklin 101 Franklin 101 Greene 14 Huntington 31 Indiana 44 Jefferson 20	Fayette	54
Fulton 7 Greene 14 Huntington 31 Indiana 44 Jefferson 20	Forest	6
Greene 14 Huntington 31 Indiana 44 Jefferson 20	Franklin	101
Indiana 44 Jefferson 20	Fulton	7
Indiana 44 Jefferson 20	Greene	14
Indiana 44 Jefferson 20	Huntington	31
		44
Juniata 12		20
	Juniata	12

Lackawanna	60
Lancaster	203
Lawrence	31
Lebanon	49
Lehigh	193
Luzerne	109
Lycoming	66
McKean	21
Mercer	44
Mifflin	23
Monroe	104
Montgomery	332
Montour	7
Northampton	171
Northumberland	43
Perry	34
Philadelphia	139
Pike	19
Potter	8
Schuylkill	58
Snyder	18
Somerset	37
Sullivan	4
Susquehanna	16
Tioga	15
Union	12
Venango	18
Warren	21
Washington	107
Wayne	12
Westmoreland	172
Wyoming	27
York	360
Out Of State	34

Total

5599

January – December 2016 Ignition Interlock Statistics

Total Number of Devices Installed
5,599


Total Number of Sober Miles Driven
63,661,974

> Total Numbers of Tests Taken


> 14,657,225

> Total Number of Failed Samples Provided

> 53,083



Time of Tests Taken



Why Ignition Interlock

- > 50-75 % OF CONVICTED DRUNK DRIVERS WILL CONTINUE TO DRIVE EVEN ON A SUSPENDED LICENSE
- > * Mothers Against Drunk Driving, February 10, 2016.
- > AN AVERAGE DRUNK DRIVER HAS DRIVEN DRUNK OVER 80 TIMES BEFORE FIRST ARREST
- > *Arrest data: Federal Bureau of Investigation, "Crime in the United States: 2014"

PA Ignition Interlock QAP Staff

C. Stephen Erni, Executive Director Eileen Lee, Director of Ignition Interlock QAP Ricky Miller, QAP Technician Russell Young, III, QAP Technician Ryan Greathouse QAP Technician Blair Walborn, QAP Technician

Pennsylvania DUI Association

2413 N. Front Street Harrisburg, PA 17110 717 238-4354

www.padui.org